

## ***Field Advisory A3213R400 3" Threaded Internal Valve***

We have recently become aware of two reports with our A3213R400 3" threaded internal valves installed in the vapor standpipe connection on Mississippi Tank transport trailers used as a loading line (liquid in). In one incident the cam attached to the pivot shaft came off resulting in the pivot shaft's release from the internal valve. This resulted in a discharge of NH<sub>3</sub> from the valve that required an emergency response by a local fire department and a plug being driven into the pivot shaft opening. We have no information on the other report.

We advise you to immediately install the attached bracket on all of our A3213R400 Series internal valves on the Mississippi Tank trailers. The bracket is designed to prevent the discharge of the pivot shaft in the unlikely event the cam is dislodged this will prevent any discharge of product from the pivot shaft opening.

- The photo below shows how the bracket is to be installed on our A3213R400 Series internal valves.



If you have any questions on this you can Ed Miller at ECII/RegO Products 336-446-7265.